

What is the bulk density divided into?

The bulk density is usually divided into untapped density and tapped density, the latter refers to the status of bulk powder after a specified tap process, and usually use a mechanical device to make the container moving up and down vertically, that is tapping the measuring cylinder.

[Back To Tap Density Tester](#)